



## **Airport Manager's Report, 2021**

**August 18, 2021**

1. The airport failed a leak test with new regulations passed in December. The above ground spill bucket where we take our jet fuel loads has two drilled holes in it from the past. The spill bucket is to be replaced by a tank certified company which I'm still trying to get quotes from.
2. Fuel prices increased on August 3<sup>rd</sup>. 100LL is hard to acquire with a 5-10 day delivery date, we are taking proper precautions not to run out.
  - **100LL - \$5.56**
  - **Jet A - \$4.71**