



Airport Manager's Report October 16, 2019

1. Ford dump truck is being refurbished
 - a. Sand blasted
 - i. Found rust through on dump bed
 - ii. Welder welding in new steel plates
 - b. Box painted
 - c. Frame hot tared
 - d. New tires
 - e. Engine errors addressed
 - f. Aligned
2. Winter prep ongoing
 - a. Big pusher box has been repaired and new cutting edge is coming
 - b. Plate being made for small pusher box to mound on John Deere
 - c. Big Snow Go snow blower is being gone over. It has not run in a year and a half
 - i. Runs good but fan shroud will rotate only one way
 1. Solenoid on hydraulic valve needs replaced. Calling in service people.
3. North fence project
 - a. Electric is now installed and waiting on fence people to finalize
 - b. Signs have been ordered
 - i. Stop! Crew and escorted passengers only
 - ii. Airport property no trespassing
4. BOA inspection Friday
5. DEP / RETTEW ongoing. Inspection resulted in no violations but many suggestions
 - a. PPC plan is still being developed and needs finalized and submitted soon
 - b. Addressing the many issues.
6. Ron's Exit. One-year notice.