



Airport Manager's Report

March 16, 2022

- 1.** Cleveland brothers repaired the cat loader hydraulic leak before the storm. Cleveland brothers still need to return for the windshield wiper repair and resealing a side window on the cab.
- 2.** I have been training John Meyers, soon to start him on his own schedule while still helping him along.
- 3.** Ray Price Ford fixed an issue with the new 250 where the plow was shorting out the dashboard when operating.